



**HYTORC HY-1XLT**

**PRESSURE/TORQUE CONVERSION CHART**

PRESSURE IN PSI				PRESSURE IN BAR
	FT. LBS.	KGM	NM	
1500	200	28	271	104
1600	214	30	290	110
1800	242	33	328	124
2000	270	37	366	138
2200	297	41	403	152
2400	324	45	439	166
2600	351	49	476	179
2800	378	52	512	193
3000	405	56	549	207
3200	431	60	584	221
3400	457	63	620	235
3600	483	67	655	248
3800	509	70	690	262
4000	535	74	725	276
4200	562	78	762	290
4400	589	81	798	304
4600	616	85	835	317
4800	643	89	872	331
5000	670	93	908	345
5200	697	96	945	359
5400	724	100	981	373
5600	751	104	1018	386
5800	778	108	1055	400
6000	805	111	1091	414
6200	832	115	1128	428
6400	859	119	1164	442
6600	886	123	1201	455
6800	913	126	1238	469
7000	940	130	1274	483
7200	967	134	1311	497
7400	994	137	1347	511
7600	1021	141	1384	524
7800	1048	145	1421	538
8000	1075	149	1457	552
8200	1101	152	1493	566
8400	1127	156	1528	580
8600	1153	159	1563	593
8800	1179	163	1598	607
9000	1205	167	1633	621
9200	1232	170	1670	635
9400	1259	174	1707	649
9600	1286	178	1743	662
9800	1313	182	1780	676
10000	1340	185	1817	690

This chart supercedes all prior version regarding this tool 03/31/2008

3508 S. County Rd 1290 Odessa, TX 79765 432-561-8481 <b>West Texas Office</b>	4802 Baldwin Blvd Corpus Christi, TX 78408 361-888-5080 <b>SW Texas Office</b>	12420 Texaco Rd Houston, TX 77013 713-453-6677 <b>Main Office</b>	2484 W. Cardinal Ave Beaumont, TX 77705 713-412-0106 <b>SE Texas Office</b>	8988 FM 2011 Longview, TX 75603 903-653-1450 <b>NE Texas Office</b>
--	---	--	--	--